



LEGEND
Street furniture & SERVICES

| | | | |
|---------------------------------------|-------------------------------|------------------------------|---------------|
| 542 Over Head Wire (LUAS) - Pylon ESB | 542 Bus Stop | 542 Bench Seat | 542 Phone Box |
| 542 Flowerbed | 542 Bollard | 542 Gas Cover | 542 Duct |
| 542 Pipe | 542 Beacon | 542 Gas Cover | 542 P Box |
| 542 Lit | 542 Coal Oil Cover | 542 Waste Bin | |
| 542 Planer | 542 Bone Hoop | 542 Hydrant | |
| 542 Gas/Utility Pole | 542 Telegraph Pole | 542 Fire Hydrant | |
| 542 Auto Train Driver | 542 CCTV Pole | 542 ESB Box | |
| 542 Postbox | 542 CCTV Camera Pole | 542 ESB Inspection Cover | |
| 542 Valve - General | 542 Lamp Post | 542 Traffic Control Box | |
| 542 Water Valve | 542 Four Manhole | 542 LUAS Technical Cabinet | |
| 542 Sluice Valve | 542 Surface Water MH | 542 Ticking Vehicle Machine | |
| 542 Air Valve | 542 Manholes | 542 Water Meter Cover | |
| 542 Stop Cock | 542 Air Conditioning Vents | 542 Telecom Inspection Cover | |
| 542 Sewer Inspection Cover | 542 Traffic Inspection Cover | 542 Monument / Toggles | |
| 542 Marker Post | 542 Cable TV Inspection Cover | 542 Tank Storage | |
| 542 Traffic Light | 542 ESAT Inspection Cover | 542 Basement MH Cover & Pops | |
| 542 Plane Aerial Mark | 542 NTL Inspection Cover | 542 Diabetic Aerial Mark | |
| 542 Smart Card Validator | 542 Excom Inspection Cover | 542 Ely for pole | |
| 542 Laminated Valve | 542 Flooding Eye | 542 Pipe Protection | |
| | | 542 Washout | |

Natural Features

| | | |
|--|--------------------|--------------------|
| 542 Surface Change | 542 Water Level | 542 Fair Way |
| 542 Lull / Dip | 542 Crown Level | 542 Green |
| 542 Bottom of Slope | 542 Invert Level | 542 Tee Box |
| 542 Top of Slope | 542 Bed Level | 542 Other |
| 542 Ditch | 542 Spoilheight | 542 Survey Station |
| 542 Water Edge / Lake / Pond | | 542 Photo point |
| 542 Hedge / Trees Drip Line / Vegetation | | |
| 542 Tree Coniferous | 542 Tree Deciduous | 542 Top of Tree |

Built Features



| | | |
|--|--|----------------------|
| 542 Building | 542 Fence | 542 Floor Level |
| 542 Edge of Road | 542 Gate | 542 Apex Height |
| 542 Kerb Bottom | 542 Road Centreline | 542 Eave's Height |
| 542 Kerb Top | 542 Top of Wall | 542 Parapet Height |
| 542 Bridge Abutment | 542 Hoarding | 542 Softie Elevation |
| 542 Bridge Deck | 542 Property Line | 542 Step Level |
| 542 Bridge Parapet | 542 Road Scar | 542 Corridor Pad |
| 542 Building Facade | 542 Top of Fence | 542 Track |
| 542 Footpath / Platform / Tram | 542 Wall / Retaining Wall | |
| 542 Damp Proof Course / Verge | 542 Railway / Tram Rail / Grating / Ramp | |
| 542 Bridge Pier / Wall & Gate Pile / LUAS Trackbed | 542 Building Canopy / Hood / Overhang | |
| 542 Cycleway / Private Landing Area | | |

Murphy Surveys Ltd. Disclaimer

The user or recipient of the survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed hereon. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed will be labelled as 'UTS'.

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or damages suffered by the Client.

The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such impression or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.



| | | |
|-----------------|--------------------|--|
| Surveyed by: DB | Date: October 2019 | Datum: Mean High |
| Drawn by: CC | Date: October 2019 | Grid System: Irish National Grid I.D. RM |
| Checked by: RV | Date: 17.10.19 | Revision: |

murphy SURVEYS
 GLOBAL CONSULTING SURVEYORS
 Topographic surveys, Measured Building Surveys, Building Civil, 2D/3D Surveys, Hydrographic Surveys, Legal Mapping, Pipeline Surveys, Services Location, Ground Penetrating Radar, Laser Scanning, Aerial Photography

Head Office
 Global House
 Kildare Business Campus
 Kildare Co. Kildare
 Ireland

Phones: (+353) 045 484040
 Fax: (+353) 045 484004
 Email: Info@murphysurveys.ie

Client: Sarah-Jane Kearney

Project: Boundary issue

Date: 17.10.2019 **Scale:** 1:250@A1

Description: Topographical Survey

Drawing Number: MSL32440_T_ITM_Rev0_02

© Copyright 2019 MURPHY SURVEYS LTD