

PHOTO: NO. 1



APPROACH TO TUBBER LANE
FROM OLD COLBRIDGE ROAD



GOLFERS CROSSING
POINT ON BEND



ROAD USERS
GOLF COURSE
AHEAD

CAUTION
GOLFERS
CROSSING

L.C.C. FRONT HOLE



PHOTO: NO. 2

PHOTO: NO. 3

OLD CALBRIDGE RD.

RESTRICTED VISION ON BEND
AT END OF TUSKILL LANE.

"FRONT"
HOLDS.



BEND ON APPROXIMATELY NORTH TURNER LANE
TOWARDS OLD GET BRIDGE ROAD

GOLEMAN'S CROSSING-POINT

GOLEMAN'S CROSSING-POINT

PHOTO: NO. 4



PHOTO: NO. 5

APPROX LOCATION PROPOSED RELOCATION
OF ENTRANCE TO GREENWAYS

PROPOSED NEW ENTRANCE

TO PROPOSED NEW

SIDE HOUSE

CROSSING FOR
GOLF CARTS,
MAINTENANCE
VEHICLES

CROSSING ROUTE FOR GOLFERS
FROM "FRONT" TO "BACK" HOUSE




PHOTO: NO. 6

TUBBER LANE FACING SOUTH

NOTE "RURAL"
NATURE OF TUBBER
LANE.



CROSSINGS BY GOLFERS.

CARS + MACHINERY / VEHICLES
CROSSING



PHOTO: NO. 7

TURBID LAND FACING
SOUTH.

PROPOSED NEW ENTRANCE
TO NEW 5 BED. HOUSE

L.G.C.
CLUBHOUSE
& FIRST 755

CROSSING ROUTE FOR GOLF CARTS
AND MAINTENANCE VEHICLES/MACHINERY

CROSSING POINT FOR GOLFERS FROM "FRONT"
TO "BACK HOLES"

PHOTO: NO. 8

TUBER LANS
FACING
SOUTH.

"
GREENWAYS."
"

PROPOSED NEW
ENTRANCE TO
"GREENWAYS"
PEDESTRIAN ACCESS.
PLANNING START NOT
KNOWN.

"
GREENWAYS"
SHAD EX.
ENTRANCE

PROPOSED LOCATION OF
NEW ENTRANCE TO NEW
S BOYHOOD HOUSE

EXISTING ENTRANCE AND
EXIT FROM "FRONT" TO LEFT
FROM GOLF CARTS +
MAINTENANCE BUILDING




PHOTO: NO. 9

EXISTING ENTRANCE SHOWN
BY TWO PROPERTIES

APPRX. LOCATION OF
RELOCATED ENTRANCE

PROPOSED ENTRANCE
TO NEW 5 BED HOUSE

CROSSING POINT FOR GOLF
CARTS + MAINTENANCE MACHINERY
& VEHICLES.



PHOTO: NO. 10

↑
CROSSING CARTS
EXITING "FRONT" HOLES
OF L.G.C.

↑
PROPOSED NEW ENTRANCE TO PROPOSED
5 BEDROOM NEW HOUSE

PLANNING STATUS OF PROPOSED ENTRANCES NOT COMPLETED



PHOTO NO. 11
TUBBER LANE
FACING
SOUTH

RURAL CHARACTER OF
TUBBER LANE

OUTSIDE EXISTING ENTRANCE

OF "GARDENWAYS"

Photo: No. 12



MAINTENANCE & DRIVEWAY ACCESS

SHARED EXISTING ACCESS TO
"GREENWAYS" & NEIGHBORING PROPERTY

PHOTO: NO. 13

WATERCOURSE / DITCH
DIRT ON APPLICANTS
SIDE OF TUBES
LAWNS



PHOTO: NO. 14

FACING NORTH
ON TUBBON LANE.

L.G.C. BACK
HOLES.



VEHICLE ILLUSTRATES
LIMITED CARRIAGEWAY
WIDTH.

NO OBVIOUS VEHICLES PASSING
SPACES DUE TO CHARACTERISTICS
OF DRAIN/DITCHES/WATER COURSES

← WATERCOURSE ON WEST SIDE
OF TUBBON LANE.



PHOTO: NO. 15
FACING NORTH ON TUBBOUR LANE
ONE OF EXISTING L.G.C.
CART CROSSING POINT

APPROX. LOCATION
OF PROPOSED LOCATION
NEW ACCESS TO 5 BED
HOUSE

APPROX. LOCATION OF PROPOSED
NEW ENTRANCE TO
TUBBOUR LANE
GARDEN WAYS

