murray & associates landscape architecture

ARBORICULTURAL INVENTORY AND IMPACT ASSESSMENT

Incorporating a

TREE PROTECTION STRATEGY

At

STRATEGIC HOUSING DEVELOPMENT, ON SITE AT MILL ROAD, SAGGART, CO. DUBLIN

FOR

Tetrarch Residential Ltd.

Murray & Associates Landscape Architecture

16 The Seapoint Building 44-45 Clontarf Road, Dublin 3 Tel: +353 (0)1 8540090 Fax: +353 (0)1 8540095

mail@murray-associates.com www.murray-associates.com

Member of the Irish Landscape Institute





Contents

Introduction	1
Scope	1
Proposed Development	
Methodology Employed	
Tree Survey Results	
Conclusions	
Disclaimers	20

Contents

Rev. No.	Issue Status	Date	Prepared By	Checked By
1	For Issue	03.11.20	MP/AG	JW
2	Revised Site Layout	19.10.21	JW	JW
3	Revised impact	18.11.21	JW	MB
	assessment			
4	For Issue	14.12.21	JW	MB

Introduction

The trees and hedgerows were surveyed on the 28th of October 2020 and the 11^{th of} November 2021 by this practice and the findings have been summarised and recorded in the following report. A number of mature trees on the development site area were re-surveyed and assessed. Some of the trees on the site will have to be removed to accommodate the development.

Scope

The site is the subject of a planning application for new residential development. The site contains a number of mature trees, and this report has been commissioned to provide an arboricultural assessment of the site to assist the design team as they prepare detailed plans for the new development. The purpose of this assessment is to provide an analysis of any potential impact of the proposed development on the existing trees and hedgerows. The report will provide recommendations for preservation and or removal of trees and hedgerows. It will present a written report on the inspection of the trees. The report will provide a tree protection plan highlighting which trees are to be removed and/or retained

This report should be read with reference to the findings summarised and recorded in the Tree and Hedgerow Assessment report, conducted on 28th October 2020 and the 11^{th of} November 2021. The report should also be read in conjunction with the following drawings:

- Landscape Plan (REF: 1829_PL_P_01)
- Tree Survey (REF. 1829_TS_P_01)
- Arboricultural Impact Plan (REF. 1829_TS_P_02)

Proposed Development

The proposed development will consist of a new residential scheme per the lodged particulars.

The site is located off the N7 route and is located to the south of this route. The site adjoins the Citywest Campus which is to the east. To the west there are single houses located along Mill Road. The main areas of trees are associated with the eastern boundary and the single house which is located off Mill Road.



Methodology Employed

An initial tree survey and visual condition assessment was on the 28^{th of} October 2020 and the 11^{th of} November 2021. For the purpose of this report the trees were assessed in accordance with BS 5837: 2012 Trees in relation to design, demolition and construction. Only trees with diameters of 75mm or greater were surveyed, and those smaller than this were noted in the survey. In accordance with section 4.4.2.3 of the British standard document where trees formed obvious groups these were assessed and recorded as groups.

Section 4.4.2.3 of BS 5837: 2012 states:

Trees growing as groups or woodland should be identified and assessed as such where the arboriculturist determines that this is appropriate. However, an assessment of individuals within any group should still be undertaken if there is a need to differentiate between them, e.g. in order to highlight significant variation in attributes (including physiological or structural condition).

NOTE: The term "group" is intended to identify trees that form cohesive arboricultural features either aerodynamically (e.g. trees that provide companion shelter), visually (e.g. avenues or screens) or culturally, including for biodiversity (e.g. parkland or wood pasture), in respect of each of the three subcategories.

The survey concentrated primarily on the significant trees located within the development area. The objective of this survey was to gather information regarding the tree's location on the proposed development site and the impact the proposed development may have on the trees. Please refer to appendix 1 for the tree inventory. Significant trees can be equated as those trees whose visual importance to the surrounding area is enough to justify special efforts to protect/preserve and whose loss would have an irremediable adverse impact on the local environment. Significance can also be placed depending on the trees age, another variable to imply significance can be the aesthetic merit of the tree based on its unusual size, intrinsic physical features or outstanding appearance or occurring in a unique location or context, and thus provides a special contribution as a landmark or landscape feature.


Tree diameters (DBH) were estimated at 1.5 meter above grade as per standard arboricultural practice. Tree height was measured with the use of a digital clinometer. The trees were categorized in accordance with BS5837:2012

Tree Survey Results

Category	Number of trees	Trees to be removed
Α	0	0
В	28	6
С	22	16
U	6	6

Table 1. Category of the Trees surveyed (BS 5837:2012, Item 4.5 Tree categorisation method)


The species composition of the site is shown on the chart below:



There are two main areas of tree cover on the site. The first is along the boundaries and these are composed of Field Maple, Sycamore, Ash and Hawthorn. These plantings will all be retained. The second area is around the existing dwelling on the southwestern boundary. This area contains a number of good specimens of Pine, Birch, Sycamore and Spruce. Of particular note are the two existing Pines 0741 and 0742 (category B1) which are situated along the old Mill Channel, and these will be retained as part of the development. These are in good condition and are very good specimens.

A third part of the site extends into the lands to the east of the site, where a path and cycle track are proposed through the existing golf club lands. There are immature stands of mixed native and trees throughout this area which were planted as part of the golf course development and the route was selected to avoid these groups.

In terms of quality the division of tree condition and quality is as shown on the charts below:



50% of trees are in fair condition, and 1/3 of the trees are in good condition. The site layout has attempted to retain as many of the trees that are in good condition as possible.

It should be noted that there are no trees within the site area of the proposed cycle and pedestrian route to the east of the main part of the development site. The closest distance at which the path passes any of the immature tree groups on the golf course is approximately 3.5m. Based on the formulae for calculation of root protection areas in BS5837 there are not likely to be any substantial roots extending from these immature trees at this distance. The recommended mitigation measure

is to carry out site investigation to determine the prior to construction. If roots are present, a "no-dig" construction methodology shall be employed for these sections of the path.

SITE PHOTOGRAPHS



Plate 1- View looking north (motorway is to the right)



Plate 2- View looking north along boundary



Plate 3- Eastern Boundary Hedgerow - General



Plate 4- Existing Trees in Northwest Corner - selection to be retained



Plate 5- Southern Boundary Hedgerow - General



Plate 6- Large Pines in Corner of site (1) to be retained

Conclusions

The proposed development will have a moderate impact on the existing tree cover on the site. Additional replanting will work to mitigate any loss of trees as a result of the proposed development. The proposed landscape plan details the planting of a significant number of new native broadleaf trees. While the short-term impact of the development will be high, in the longer term the new planting will replace the existing tree cover.

There will be no impact on the trees in the golf course area to the east of the main part of the site. The path has been designed to avoid impact on these trees. If necessary, where the path passes closest to trees, the path in this area will be constructed with no excavation to avoid any possible disturbance to the trees ("no-dig" construction methodology as outlined in BS5837).

Tree Survey Tables

Tree #	Species Botanical name	Size dia. (cm)	HT. (m)	Crown Sp.	Age class	Structural/ Physiological Observations &PMR	Impact of development	Remedial works	Category	R.P.A. (M Radius)
				N=2.3						
				E=2.3	Over-					
709	Fraxinus sp.	63	5	S=2.3 W=2.3	mature	Poor, Poor	To be retained	n/a	C3	7.56
709	Γιαχίπιος δρ.	03)	VV=2.3 N=2.3	mature	P001, P001	TO be retained	II/a	CS	7.50
				E=3.2						
				S=4	Over-					
710	Fraxinus sp.	40.57	7	W=1.1	mature	Poor, Poor	To be retained	n/a	C3	4.87
				N=5						
				E=1.1						
744	Acer		_	S=3.2	Over-		_ , , , ,		00	- 07
711	pseudoplatanus	43.93	5	W=1.1	mature	Poor, Poor	To be retained	n/a	C3	5.27
				N=3 E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
	7.1007.00.7777000.70	1		N=3	mataro	i dii, i dii	10 20 Totalifod	11,4		1.0
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
				N=3						
				E=1	Semi-					
714	Acer campestre	15	3	S=2 W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
7 14	Acer campesire	13	1	N=3	mature	i aii, i aii	TO be retained	II/a	DZ	1.0
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
				N=3						
				E=1	0:					
744	A	1		S=2	Semi-	Fair Fair	To be noteined	-1-	DO	4.0
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8

		1	1	T	1	T		1		
				N=3						
				E=1						
	_			S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
				N=3						
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
				N=3						
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
						,				
				N=3						
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
				N=3						
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
				N=3						
				E=1						
				S=2	Semi-					
714	Acer campestre	15	3	W=1.5	mature	Fair, Fair	To be retained	n/a	B2	1.8
	,			N=2.9						
				E=3.5			To be removed to			
	Acer			S=3.7			facilitate the			
715	pseudoplatanus	82	8	W=3.6	Mature	Fair, Fair	development	n/a	C1	n/a
	,			N=3.3		,	·		_	
				E=1.4			To be removed to			
	Acer			S=3.9			facilitate the			
716	pseudoplatanus	48	8	W=1.6	Mature	Fair, Fair	development	n/a	C1	n/a
7.0	podadopiatariao	+		N=3.3	mataro	1 40, 1 40	actoropinoni	1,1,54	<u> </u>	1.,, G
				E=1.4			To be removed to			
	Acer			S=3.9			facilitate the			
717	pseudoplatanus	51	8	W=1.6	Mature	Fair, Fair	development	n/a	C1	n/a
, , , ,	pocadopialarido	1 3 ±	<u> </u>	VV-1.0	Mature	1 all, 1 all	Lacyclopinion	Пла	<u> </u>	11/4

				N=3.3						
				E=1.4			To be removed to			
	Acer			S=3.9			facilitate the			
718	pseudoplatanus	64	8	W=1.6	Mature	Fair, Fair	development	n/a	C1	l n/a
7.10	росицориципис	<u> </u>	+	N=3	Mataro	r an, r an	development	TI/G	-	11/4
				E=1.4			To be removed to			
	Acer			S=3.9			facilitate the			
719	pseudoplatanus	64	8	W=1.6	Mature	Fair, Fair	development	n/a	C1	n/a
1.0	poodaopiatairao		+	N=3.3	- mataro		goverepment	11, 4	 	1,, 4
				E=1.4			To be removed to			
	Acer			S=3.9			facilitate the			
720	pseudoplatanus	110.70	8	W=1.6	Mature	Fair, Fair	development	n/a	C1	n/a
				N=2.5		,				
				E=1.4			To be removed to			
	Acer			S=2.9			facilitate the			
721	pseudoplatanus	53	8	W=3	Mature	Fair, Fair	development	n/a	C1	n/a
				N=2.3						
				E=1.4			To be removed to			
	Acer			S=2			facilitate the			
722	pseudoplatanus	35	6	W=1.6	Mature	Fair, Fair	development	n/a	C1	n/a
				N=2.3			To be removed to			
	4			E=1.4						
700	Acer	4.22		S=4.8			facilitate the	,	0.4	,
723	pseudoplatanus	122	8	W=1.6	Mature	Fair, Fair	development	n/a	C1	n/a
				N=2.4			To be removed to			
	Cupressus			E=2.4			facilitate the			
724	•	46	6	S=2.7	Mature	Fair, Fair		n/o	В3	n/a
124	macrocarpa	46	0	W=2.8	Mature	raii, raii	development	n/a	DO	11/a
				N=2.3 E=2.7			To be removed to			
	Cupressus			S=2.7			facilitate the			
725	macrocarpa	127.22	6	W=2.6	Mature	Fair, Fair	development	n/a	В3	n/a
120	madiodalpa	127.22	+	N=2	Watare	1 Gir, 1 Gir	development	11/4	50	11/4
				E=2			To be removed to			
				S=2			facilitate the			
726	Picea omorika	63	7	W=4	Mature	Good, Good	development	n/a	B2	n/a
	1 :				1		22.2.001110111	1 - "		,

	<u> </u>			N 0		T				
				N=2			To be removed to			
				E=2	Early		facilitate the			
707	Fravinus an	29	6	S=2	,	Door Door		10/0	C3	2/2
727	Fraxinus sp.	29	В	W=3	mature	Poor, Poor	development	n/a	U3	n/a
				N=3.4			To be removed to			
	Cupressus			E=3.2	Early		facilitate the			
700	· ·	0.7	6	S=3.3	-	Cood Cood		10/0	B2	10.44
728	macrocarpa	87	6	W=2.3	mature	Good, Good	development	n/a	BZ	10.44
				N=2			To be removed to			
				E=2 S=2			facilitate the			
729	Picea omorika	46	9	S=2 W=4	Mature	Good, Good		n/a	B1	5.52
129	Picea Omonka	40	9	N=3.1	Mature	G000, G000	development	II/a	ы	5.52
				E=2.8			To be removed to			
				S=3.2			facilitate the			
730	Pinus sp.	63	11	W=3.2	Mature	Good, Good	development	n/a	B2	7.56
730	T IIIus sp.	03	111	N=4	Mature	Good, Good	development	11/a	DZ	7.50
				E=5						
				S=3						
731	Betula pendula	56	11	W=3.9	Mature	Good, Good	To be retained	n/a	B1	6.72
701	Botara porradra			N=0.6	Mataro	0000, 0000	10 po rotamou	Tira	<u> </u>	0.72
				E=0.7						
				S=0.65						
732	Larix decidua	42	9	W=0.8	Mature	Good, Good	To be retained	n/a	В3	5.04
				N=4						
				E=5						
				S=5						
733	Betula pendula	53	9	W=3.9	Mature	Good, Good	To be retained	n/a	B1	6.36
	,			N=3						
				E=3						
	Acer			S=4.1	Early					
734	pseudoplatanus	29	4	W=3	mature	Good, Good	To be retained	n/a	B2	3.48
				N=4.1						
				E=3.4			To be removed to			
	Prunus			S=3.4			facilitate the			
735	'Amanogawa'	39	3	W=4.1	Mature	Poor, Poor	development	n/a	U	n/a

				N=2.3						
				N-2.3 E=2.1			To be removed to			
	Laburnum			S=2.4	Over-		facilitate the			
736	amygaloides	36.06	3	W=2.3	mature	Poor, Poor	development	n/a	U	n/a
				N=2			To be removed to			
				E=4.9 S=2	Early		facilitate the			
737	Fraxinus sp.	54	8	S=2 W=2	mature	Good, Good	development	n/a	В3	6.48
707	Ταλίπαο ορ.	34		N=2	mataro	Good, Good		11/4	В	0.40
				E=4.9			To be removed to			
				S=2	Early		facilitate the			
738	Fraxinus sp.	71	8	W=2	mature	Good, Good	development	n/a	B3	n/a
				N=1.95						
İ				E=1.95 S=2.25	Early					
739	Fraxinus sp.	36	7	W=2.25	mature	Fair, Fair	To be retained	n/a	C3	n/a
	- resurrere ejer			N=4.7		,		1		1.,, 5.
I				E=4.2						
= 40	Cupressus			S=4.4				,		,
740	macrocarpa	80	9	W=4.6	Mature	Fair, Fair	To be retained	n/a	C2	n/a
				N=3.95 E=4.24						
				S=3.9						
741	Pinus sp.	72	13	W=3.9	Veteran	Good, Good	To be retained	n/a	B1	n/a
				N=3.95		- , -				
				E=2						
740	5.		4.0	S=3					D4	,
742	Pinus sp.	82	13	W=2	Veteran	Good	To be retained	n/a	B1	n/a
				N=2 E=2						
	Cupressus			S=2.5	Over-					
743	macrocarpa	58	9	W=2.5	mature	Poor, Poor	To be retained	n/a	C3	n/a
	,			N=3.2						
				E=3.4	•					
711	Cupressus	40		S=3.2	Over-	Daar Daar	Talka nakain ad		00	
744	macrocarpa	49	6	W=3.4 N=3	mature	Poor, Poor	To be retained	n/a	C3	n/a
				N=3 E=3	Early					
745	Fraxinus sp.	42	6	S=2.8	mature	Good, Good	To be retained	n/a	B2	n/a
	1 1 0.5 1 0.0 0 0 0 0		1 -				1 - 20	1		

				W=2.8						
746	Fraxinus sp.	38	9	N=2.2 E=2.3 S=2.2 W=2.3	Early mature	Good, Good	To be removed to facilitate the development	n/a	C1	n/a
746	Fraxinus sp.	38	9	N=2.1 E=2.3 S=2.1 W=2.3	Early mature	Good, Good	To be removed to facilitate the development	n/a	C2	n/a
746	Fraxinus sp.	38	9	N=3.1 E=2.5 S=2.7 W=2.6	Early mature	Good, Good	To be removed to facilitate the development	n/a	C2	n/a
747	Acer pseudoplatanus	54	7	N=5 E=4 S=4 W=4	Early mature	Fair, Fair	To be retained	n/a	B1	6.48
748	Fraxinus sp.	108.93	8	N=3.4 E=3.2 S=3.6 W=3.4	Over- mature	Poor, Poor	To be removed on safety grounds	n/a	C3	n/a
749	Acer pseudoplatanus	49	7	N=4.5 E=4.3 S=4.4 W=3.6	Early mature	Fair	To be retained	n/a	C1	5.88







Figure 4 - Proposed landscape layout plan (Page 1/2) - Main Development Area

Residential Development at Mill Road



Figure 5 - Proposed landscape layout plan (Page 2/2) – Eastern Part of Site with Path / Cycle Route

Note that this illustrates that there are no trees within the red line of the site and the nearest trees are c. 3.5m from the nearest edge of the path, so there is no predicted impact to the trees arising in this location which would result in loss of trees due to construction works.



Disclaimers

This report is intended solely for the benefit of the parties to whom it is addressed, and no responsibility is extended to any third party for the whole or any part of its contents. The conclusions and recommendations in this report are only valid for a period of one year. This period of validity may be reduced in the case of any change in conditions to or in proximity to the tree. In the event of adverse weather conditions, there is the possibility of any tree despite good report surveys, falling over.

In the event of a falling tree causing damage to residential or non-residential buildings in their proximity, no liability will attach to this firm, in the event of damage by such trees, to any person, any building public or private, or any mechanical vehicle or otherwise. Recommendations made in this report are subject to the knowledge and expertise of the qualified Arborist that carried out the above inspections.

Signed		

Dated: 14.12.2021

John Ward

ISA Certified Arborist