

info@treespace.ie www.treespace.ie

Cork & Dublin Office: Unit P5, Marina Commercial Park, Centre Park Road, Cork

23/01/2023

RE: Planning Ref. SD21A/0241 – Condition 11

ear Sirs,

n response to your request for official communication on the tree protection review for the site subject of ne permission as granted under Planning Ref. SD21A/0241. I can confirm that the pre commencement site neeting regarding the tree protection alignments was completed on the 23rd of January 2023. The following bservations and recommendations were discussed with the main contractor:

- The tree protection fencing alignments have been fully installed, and they comply with the tree protection plan by Arborists Associates (Dwg No.PFP002).
- The fencing specification that has been erected is adequate and it complies with the British Standard BS 5837:2012 Trees in Relation to Design, Demolition and Construction -Recommendations.
- The main contractor has agreed to brief all contractors visiting the site on the layout of the tree protection fencing.

ased on the agreed fencing alignments the tree protection measures are sufficient and the ground /orks can commence.

)ur site visit report is appended to this letter.

ours sincerely

(an 065-

Conor O Callaghan

Checklist Detail

#6 - 2023.01.23 - Arboriculturist - Tree Monitoring Form

Status	Completed			
Created date	Jan 23, 2023			
Scheduled date	Jan 23, 2023			
Started date	Jan 23, 2023			
Completed date	Jan 24, 2023			
Туре	Quality			
Description	Arborists Checksheet			
Location				
Template	2023.XX.XX - Arboriculturist - Tree Monitoring Form [V4]			
Linked documents				
Linked assets				
Assigned to	Conor O Callaghan (Treespace)			
Creator	Michael Beagan (Ramboll UK)			
Section assignees	Conor O Callaghan (Treespace)			

Sections	Items	Issues	Conforming	Non- conforming	N/A	To be answered
1/1	4/4	0	1	0	0	0

1. Arborist - Site Review

Assigned to
Conor O Callaghan (Treespace) • (4/4)

1.1
Date of Site Visit

Image: Ima

Created with Autodesk[®] Construction Cloud[™] on Jan 24, 2023 at 7:39 AM IST



ODone



Images





photo_1674492496442.jpg Added on Jan 23, 2023 4:48 PM Added by Michael Beagan 9fb8949a-c3e3-420a-a60d-bb57907f1784.png Taken on Jan 23, 2023 9:36 AM Added on Jan 23, 2023 1:51 PM Added by Michael Beagan




f3ef78ba-a001-4cca-97c9-8ffd74c1cbe9.png Taken on Jan 23, 2023 9:35 AM Added on Jan 23, 2023 1:51 PM Added by Michael Beagan d18ed75d-cf86-4f2b-9e5e-8536a1708691.png Taken on Jan 23, 2023 12:18 PM Added on Jan 23, 2023 1:50 PM Added by Michael Beagan



ae1d7cf2-af48-4052-ab42-2a424338b221.png Taken on Jan 23, 2023 12:18 PM Added on Jan 23, 2023 1:50 PM Added by Michael Beagan



bb803c58-d353-4919-9680-8d374b5ddf44.png Taken on Jan 23, 2023 12:17 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



245a6a2e-ffa0-445e-af41-e2ccb51e346b.png Taken on Jan 23, 2023 12:15 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan b4984dbd-8cb5-415b-ab41-58c06ae388a2.png Taken on Jan 23, 2023 12:15 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



ebdc80fc-eced-4d3f-8ecc-5b3f21af5bf0.png Taken on Jan 23, 2023 12:14 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



212582a5-4927-44db-9740-68963ba19a85.png Taken on Jan 23, 2023 12:10 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan

Images





63ef6371-4e5a-424a-8e07-332d99a77648.png Taken on Jan 23, 2023 12:10 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



d1332e9b-ff92-4173-b6c2-4579d508bc4e.png Taken on Jan 23, 2023 12:10 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



9db829da-c263-4006-9e1f-f09d2f32b05b.png Taken on Jan 23, 2023 12:10 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan 837485d9-02c6-473f-b14c-def867444fb5.png Taken on Jan 23, 2023 12:09 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



7fb8488e-871c-4c12-9182-49dbfb0ebec3.png Taken on Jan 23, 2023 12:08 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



f13f0b26-ced8-4688-b6a0-2c847dea3cde.png Taken on Jan 23, 2023 12:08 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan

Images





72ce33f4-fc39-4095-9712-2aa017dc3d43.png Taken on Jan 23, 2023 12:08 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan





6e220c53-20e1-4af8-9428-ae35c178c765.png Taken on Jan 23, 2023 12:05 PM Added on Jan 23, 2023 1:49 PM Added by Michael Beagan



4f7300a1-6ffb-405e-bb4b-375556fda493.png Taken on Jan 23, 2023 12:05 PM Added on Jan 23, 2023 1:48 PM Added by Michael Beagan

8a353caf-fa77-4b06-89be-f134f4a1b898.png Taken on Jan 23, 2023 12:05 PM Added on Jan 23, 2023 1:48 PM Added by Michael Beagan



8615460c-33c7-4bbf-8eca-9555caee9e3d.png Taken on Jan 23, 2023 12:23 PM Added on Jan 23, 2023 1:48 PM Added by Michael Beagan



1.4 Any Recommended Actions

Small adjustments were required on site during the inspection. These were addressed and inspected as complete.

Sig	natures		2/2 Signed			
1	Required by	Not specified				
		CON O COS				
	Signed by Conor 'Callaghan from Tree Space on Jan 24, 2023 at 6:30 AM IST					
2	Required by	Not specified				
	Michael 1999					
	Signed by Michael Beagan from Ramboll on Jan 24, 2023 at 7:25 AM IST					