



LEGEND

Street Furniture & Services

5.12	Over Head Wires (LIAS) - Pylon ESB	5.12	Fixed Sign	5.12	Phone Box
5.12	Flashed	5.12	Bus Stop	5.12	Barrel Seal
5.12	Pipe	5.12	Boiler	5.12	Post
5.12	Light	5.12	Beacon	5.12	Kiosk
5.12	Barrier	5.12	Coal/Ashe Cover	5.12	Gas Boiler
5.12	Pump	5.12	Bore Hole	5.12	Gas Meter
5.12	Trial Pit	5.12	Electricity Pole	5.12	Waste Bin
5.12	Bus/Tram Shelter	5.12	Telegraph pole	5.12	Hydrant
5.12	Postbox	5.12	CCTV Pole	5.12	Fire Hydrant
5.12	Valve - General	5.12	CCTV Camera Pole	5.12	ESB Box
5.12	Water Valve	5.12	Lamp Post	5.12	ESB Inspection Cover
5.12	Gas Valve	5.12	Foul Manhole	5.12	Traffic Control Box
5.12	Sludge Valve	5.12	Surface Water MH	5.12	LIAS Technical Cubicle
5.12	Air Valve	5.12	Manholes	5.12	Ticket Vending Machine
5.12	Stop Cook	5.12	Air Conditioning Vents	5.12	Water Meter Cover
5.12	C/P Post	5.12	Services Inspection Cover	5.12	Water Meter Cover
5.12	Manhole Post	5.12	Traffic Inspection Cover	5.12	Water Meter Cover
5.12	Lighting	5.12	Canal Inspection Cover	5.12	Water Meter Cover
5.12	Water Meter	5.12	ESB Inspection Cover	5.12	Water Meter Cover
5.12	Phone Aerial Mast	5.12	NIT Inspection Cover	5.12	Water Meter Cover
5.12	Smart Carro Valves	5.12	Electric Inspection Cover	5.12	Water Meter Cover
5.12	Unknown Valve	5.12	Footing Eye	5.12	Water Meter Cover

Natural Features

5.12	Surface Change	5.12	Water Level	5.12	Golf
5.12	Land Drain	5.12	Crown Level	5.12	Fair Way
5.12	Bottom of Slope	5.12	Invert Level	5.12	Green
5.12	Top of Slope	5.12	Field Level	5.12	Green
5.12	Ditch	5.12	Spotlight	5.12	Other
5.12	Water Edges / Lanes / Ponds	5.12	Tree Deciduous	5.12	Survey Station
5.12	Hedge / Trees / Drip Lanes / Vegetation	5.12	Tree Deciduous	5.12	Photo Point
5.12	Tree Coniferous	5.12	Tree Deciduous	5.12	Top of Tree

Built Features

5.12	Building	5.12	Fence	5.12	Floor Level
5.12	Edge of Road	5.12	Gate	5.12	Apex Height
5.12	Werk Bottom	5.12	Road Crossover	5.12	Eaves Height
5.12	Werk Top	5.12	Top of Wall	5.12	Parapet Height
5.12	Bridge Abutment	5.12	Hoarding	5.12	Soft Elevation
5.12	Bridge Deck	5.12	Property Line	5.12	Step Level
5.12	Bridge Pier/Post	5.12	Road Scar	5.12	Concrete Pad
5.12	Building Facade	5.12	Top of Fence	5.12	Track
5.12	Footpath / Platform Train & Tram	5.12	Wall / Retaining Wall	5.12	Wall / Retaining Wall
5.12	Damp Proof Course / Verge	5.12	Halfway / Team Path / Crating / Flange	5.12	Halfway / Team Path / Crating / Flange
5.12	Bridge Pier / Wall & Gate Pillar / LIAS Tracked	5.12	Building Canopy / Roof / Overhang	5.12	Building Canopy / Roof / Overhang
5.12	Cycleway / Private Landing Area	5.12		5.12	

Murphy Surveys Ltd. Disclaimer

The user or recipient of this survey data understands and acknowledges that this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Whenever possible, areas unable to be surveyed will be labelled as 'UTIS'.

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or damages suffered by the Client.

The Client must promptly notify the Company of any errors in mapping of which it becomes aware, if misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.

Map of Site Location

Surveyed by:	L2	Date:	17.06.2021	Datum:	Main Head
Drawn by:	CC, PI	Date:	17.06.2021	Grid System:	
Checked by:	PR	Date:	17.06.2021	Irish National Grid ID:	17H553

SOCIETY OF CHARTERED SURVEYORS IRELAND

EUROPEAN GPR ASSOCIATION

RICS the mark of the surveying profession

THE SURVEY ASSOCIATION

Murphy GEOSPATIAL

Topographic surveys, Measured Building Surveys, Heritage, Archaeological Surveys, Hydrographic Surveys, LiDAR Mapping, Pipeline Surveys, Services Location, Ground Penetrating Radar, Laser Scanning, Aerial Photography

Kildare Cork Dublin Belfast Glasgow Manchester London

Head Office: Phone: (+353) 045 484040
 Kilsallan Business Campus: Fax: (+353) 045 484004
 Kilsallan Co. Kildare: Email: info@murphysurveys.com

Client: Greenwalk Development Ltd

Project: Topo GPR - Kingswood lands

Date: 17.06.2021 Scale: As Shown @ A

Description: Elevations

Drawing Number: MGL41890_EL_ITM_Rev1-1

Copyright 2021 MURPHY GEOSPATIAL LTD