

LEGEND

Street furniture & Services

Over Head Wires (LMS)	Pylon ESS	Street Sign	Phone Box
Flowerbed	Bus Stop	Bench Seat	Out
Pipe	Boiler	Kiosk	Gas Cover
Lin	Beacon	Gully	C.P. Box
Barrier	Coastline Cover	UG (The Park View)	
Pump	Box Hole	Waste Bin	
Hydrant	Electricity Pole	Hydrant	
Gas/Term. Shelter	Telegraph pole	Fire Hydrant	
Postbox	CCS Pole	ESR Box	
Valve - General	CCTV Camera Pole	ESR Inspection Cover	
Water Valve	Lamp Post	Traffic Control Box	
Gas Valve	Foul Manhole	LUAS Technical Cubicle	
Shut-off Valve	Surface Water MH	Licker Vending Machine	
Air Valve	Murholes	Water Meter Cover	
Stop Clock	Air Conditioning Vents	Telecom Inspection Cover	
Post	Services Inspection Cover	Murkover 17.6.05	
Marker Post	Traffic Inspection Cover	Tank Storage	
Traffic Light	Cable TV Inspection Cover	Basement, MH, Cover & Pipe	
Parking Meter	ESAT Inspection Cover	Dished Aerial Mark	
Plane Aerial Mark	NFL Inspection Cover	Stay for pole	
Smart Card Validator	Elcom Inspection Cover	Pipe Protection	
Unknown Valve	Flooding Eye	Washout	

Natural Features

Surface Change	Water Level	Golf
Land Drain	Crown Level	Fair Way
Bottom of Slope	Invert level	Green
Top of Slope	Bed Level	Tree Box
Ditch	Spotheight	Other
Water Edge / Lake / Pond		Survey Station
Hedge / Trees Dip Line / Vegetation		Photo point
Tree Coniferous	Tree Deciduous	Top of Tree

Built Features

Roads & Road Markings



Building	Fence	Floor Level
Edge of Road	Gate	Apex Height
Kerb Bottom	Road Centreline	Flame Height
Kerb Top	Top of Wall	Persepet Height
Design Alignment	Hoarding	Soft Elevation
Bridge Deck	Property Line	Stop Level
Bridge Pier/Post	Road Scar	Concrete Pad
Building Facade	Top of Fence	Track
Footpath / Platform Train & Tram	Wall / Retaining Wall	
Damp Proof Course / Verge	Railway / Tram Rail / Gating / Ramp	
Bridge Pier / Wall & Gate Pillar / LUAS Trackbed	Building Canopy / Roof / Overhang	
Cycleway / Paths Landing Area		

Murphy Surveys Ltd. Disclaimer

The user or recipient of this survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed will be labelled as "UTS".

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential losses or damages suffered by the Client.

The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.



Surveyed by: LZ	Date: 17.05.2021	Datum: Main Head
Drawn by: CC, PI	Date: 25.05.2021	Grid System: IRTN1983
Checked by: PV	Date: 26.05.2021	Proj. Method: Grid

Revisions

No.	Date	Description
1	16.05.2021	Final Drawing
1	17.05.2021	Spot levels on granite behind wall at south-sided
2	23.05.2021	Windows details added.

SOCIETY OF CHARTERED SURVEYORS IRELAND

EUROPEAN GPR ASSOCIATION

RICS the mark of proficiency worldwide

THE SURVEY ASSOCIATION the mark of professional excellence

Murphy GEOSPATIAL

Topographic surveys, Measured Building Surveys, Setting-Out, As-Built Surveys, Hydrographic Surveys, Legal Mapping, Pipeline Surveys, Boundary Location, Ground Penetrating Radar, Laser Scanning, Rectified Photography

Kildare Cork Dublin Belfast Glasgow Manchester London

Client: Greenwalk Development Ltd

Project: Topo GPR - Kingswood lands

Date: 26.05.2021 **Scale:** 1:250@A1

Description: Topographical Survey

Drawing Number: MGL41890_T_ITM_Rev2-1

© Copyright 2021 MURPHY GEOSPATIAL LTD