



This Drawing Must Be Read in Conjunction with the Associated Arboricultural Report

This Drawing is Copyright - © The Tree File 2022

Tandys Lane Village Tree Impacts Plan 1/1 Scale 1:500 @ A1

This is a colour coded drawing that will be difficult or impossible to interpret if reproduced in black and white

Ashgrove House  
26 Foxrock Court  
Dublin 18  
D18 R2K1



Mob. 086-3819011  
e-mail - thetreefile@eircom.net

Colour Coding of Tree Retention or Removal

- Trees Intended for Retention - Solid Green Crown Outline
- Trees Intended for Removal in Conjunction With Development Works - Broken Pink Crown Outline
- Hedge or Group Intended for Retention - Solid Green Crown Outline
- Hedge or Group Intended for Removal in Conjunction With Development Works - Broken Pink Crown Outline

- Tree Lane
- Hedges
- Scrub and Thicket

Colour Coding of Tree Categories

- Category "A" Trees (Green Button) Excellent Quality Trees
- Category "B" Trees (Blue Button) Good Quality Trees
- Category "C" Trees (Grey Button) Mediocre to Poor Quality Trees
- Category "U" Trees (Red Button) Dead, Dying or Otherwise Compromised Trees that are Unsustainable.

Graphic Representation of Tree Form, Balance and Protection Zone

- Canopy Extent
  - Cardinal Radii
  - Category Code
  - Stem Circumference
  - Root Protection Area (RPA)
- Canopy is drawn to account for any natural asymmetry or imbalance. Crown Representation is scaled to account for north, east, west and south radii.
- Root Protection Area (RPA)  
This area relates the "RPA" radius as defined in the Tree Survey Table and is measured from the tree centre. This area defines the preliminary Construction Exclusion Zone (CEZ) that must be protected by fencing from the potentially damaging affects of construction activity.

Client: Quintain Developments Ireland Ltd.

Scale: 1:500 @ A1 Date: April 2022

Project: Tree Survey, Tandys Lane Village, Adamstown, Co Dublin

Description: Tree Impacts Plan

Drawing Title: Tandys Lane Village Tree Impacts Plan