

	This drawing is to be read in conjunction with the respective arboricultural schedules and reports relevant to this project. Where contradictions between this drawing and any other design information becomes apparent, the respective authors should be contacted immediately. It is the responsibility of the main site contractor to check and verify all information and measurements onsite and confirm prior to the commencement of works, and to ensure that all site operatives work in accordance with respective arboricultural reports and BS5837:2012, Trees in relation to design, demolition and construction.
	BS5837:2012 Tree Categorisation
	Category A Trees of high quality with an estimated remaining life expectancy of at least 40 years
	Category B        Trees of moderate quality with an estimated life expectancy of at least 20 years
	Category C Trees of low quality with an estimated life expectancy of at least 10 years, or young trees with a stem diameter below 150mm
	Category U Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years
	Key      Image: Moot Protection Areas      The minimum area around a tree deemed to contain sufficient roots and rooting volume to maintain the trees viability.      Tree, Shrub or Hedgerow Group.
	Reference Number for Tree, Group or Hedgerow.
	Tree Group G628 to be removed highlighted in grey and dashed.
	Excavation works within tree RPA to be carried out under arboricultural supervision.
	Application site boundary.
NEIGHBOURING	
	0 5m 10m 15m 20m 25m
	Revision  Date  Description    Title:
	Tree Removals & Protection Plan
	Project: Bancroft View SHD
	Client: Greenhills Living Ltd.
	Date:  May 2022  Scale:  Status:    Drawn by:  CMcC  1:250 @ A1  Planning
ACA	Dwg ref:      Rev:        220202-P-11      -
ADJACENT BUILDIN	CHARLES MCCORKELL ARBORICULTURAL CONSULTANCY
	T; 085 843 7015 / E; info@cmarbor.com / W; www.cmarbor.com