



LEGEND			
Street furniture & Services			
5.12 Over Head Wires (LIAS) - Flyon ESB	5.12 Bus Stop	5.12 Road Sign	5.12 Phone Box
5.12 Flowerbed	5.12 Bench Seat	5.12 Bench Seat	5.12 Duct
5.12 Pipe	5.12 Bollard	5.12 Kiosk	5.12 Gas Cover
5.12 Litter Bin	5.12 Easement	5.12 Gully	5.12 P Box
5.12 Barrier	5.12 Coalhole Cover	5.12 Utility	5.12 Waste Bin
5.12 Pump	5.12 Bone Hole	5.12 Hydrant	5.12 Hydrant
5.12 Trial Pit	5.12 Electricity Pole	5.12 Hydrant	5.12 Hydrant
5.12 Bus/Tram Shelter	5.12 Telegraph pole	5.12 Hydrant	5.12 Hydrant
5.12 Postbox	5.12 CCTV Pole	5.12 Hydrant	5.12 Hydrant
5.12 Valve - General	5.12 CCTV Camera Pole	5.12 Hydrant	5.12 Hydrant
5.12 Waste Valve	5.12 Lamp Post	5.12 Hydrant	5.12 Hydrant
5.12 Gas Valve	5.12 Fluid Manhole	5.12 Hydrant	5.12 Hydrant
5.12 Sluice Valve	5.12 Surface Water MH	5.12 Hydrant	5.12 Hydrant
5.12 Air Valve	5.12 Manholes	5.12 Hydrant	5.12 Hydrant
5.12 Stop Cock	5.12 Air Concoching Vents	5.12 Hydrant	5.12 Hydrant
5.12 C/P Post	5.12 Services Inspection Cover	5.12 Hydrant	5.12 Hydrant
5.12 Marker Post	5.12 Traffic Inspection Cover	5.12 Hydrant	5.12 Hydrant
5.12 Traffic Sign	5.12 Cable TV Inspection Cover	5.12 Hydrant	5.12 Hydrant
5.12 Parking Meter	5.12 ESB Inspection Cover	5.12 Hydrant	5.12 Hydrant
5.12 Phone Aerial Mast	5.12 NTL Inspection Cover	5.12 Hydrant	5.12 Hydrant
5.12 Smart Card Validator	5.12 Erom Inspection Cover	5.12 Hydrant	5.12 Hydrant
5.12 Unknown Valve	5.12 Flooding Eye	5.12 Hydrant	5.12 Hydrant
Natural Features			
5.12 Surface Change	5.12 Water Level	5.12 Golf	5.12 Fair Way
5.12 Land Drain	5.12 Crown Level	5.12 Green	5.12 Green
5.12 Bottom of Slope	5.12 Invert Level	5.12 Tee Box	5.12 Tee Box
5.12 Top of Slope	5.12 Bed Level	5.12 Other	5.12 Other
5.12 Gully	5.12 Spot Height	5.12 Survey Station	5.12 Survey Station
5.12 Water Edge / Lake / Pond	5.12 Tree Deciduous	5.12 Top of Tree	5.12 Top of Tree
5.12 Hedge / Trees Dip Line / Vegetation	5.12 Tree Deciduous	5.12 Top of Tree	5.12 Top of Tree
5.12 Tree Coniferous	5.12 Tree Deciduous	5.12 Top of Tree	5.12 Top of Tree
Built Features			
Roads & Road Markings			
5.12 Building	5.12 Fence	5.12 Floor Level	5.12 Floor Level
5.12 Edge of Paved	5.12 Gate	5.12 Eaves Height	5.12 Eaves Height
5.12 Kerb Bottom	5.12 Road Centreline	5.12 Flagpole Height	5.12 Flagpole Height
5.12 Kerb Top	5.12 Top of Wall	5.12 Soft Elevation	5.12 Soft Elevation
5.12 Slope Ascent	5.12 Hoarding	5.12 Step Level	5.12 Step Level
5.12 Slope Descent	5.12 Property Line	5.12 Concrete Paved	5.12 Concrete Paved
5.12 Slope Parapet	5.12 Road Scar	5.12 Track	5.12 Track
5.12 Building Facade	5.12 Top of Fences		
5.12 Hoopern / Platform Train & Tram	5.12 Wall / Hearing Wall		
5.12 Damp Proof Course / Verge	5.12 Railway / Train Rail / Crossing / Ramp		
5.12 Bridge Pier / Wall & Gate Pillar / LIAS Trackbed	5.12 Building Canopy / Roof / Overhang		
5.12 Cycleway / Private Landing Area			

Murphy Surveys Ltd. Disclaimer

The user or recipient of this survey data understands and acknowledges that this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Whenever possible, areas unable to be surveyed will be labelled as 'UTS'.

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or damages suffered by the Client.

The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such impression or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.

North

Site Location

Map Sheet Layout

2

Surveyed by: EB	Date: October 2019	Datum: Irish Mean Sea Level	Grid System: ITRN
Drawn by: CC	Date: October 2019	Grid System: Irish National Grid	ITRN
Checked by: PK	Date: 17.10.19	Phonons	
No. Date	Description		
0	17.10.19	First Drawing	

murphy SURVEYS
 GLOBAL CONSULTING SURVEYORS
 Topographic surveys, Measured Building Surveys, Setting-Out, As-Built Surveys, Hydrographic Surveys, Legal Mapping, Pipeline Surveys, Services Location, Ground Penetrating Radar, Laser Scanning, Aerial Photography
 Kildare Cork Belfast Glasgow London
Head Office
 Global House
 Kildare Business Campus
 Kildare Co. Kildare
 Ireland
 Phones: (+353) 045 484040
 Fax: (+353) 045 484004
 Email: info@murphysurveys.ie

Client:	Sarah-Jane Kearney
Project:	Boundary issue
Date:	17.10.2019
Scale:	1:250@A1
Description:	Topographical Survey
Drawing Number:	MSL32440_T_ITM_Rev0_01

© Copyright 2019 MURPHY SURVEYS LTD