

TAKE PICTURE OF WORKS CARRIED OUT

SIGNATURE OF TOP MAN

SIGNATURE ON COMPLETION OF WORKS

Take picture of grease trap

Signature

Sketch

Take photo

Engineer sign-off



Docket No: WC0001		DYNO-ROD <i>Drain Cleaning, Inspection & Repair</i>	
Carrier: Crowley Services Dublin Ltd. T/A Dyno-Rod		Registered Address: Unit 49 Boeing Road Santry, Dublin 17. Tel: 01 663 0844 e-mail: dublin@dyno-rod.ie	
Cork Office: Unit P1, Marina Commercial Park, Centre Park Road, Cork. Tel: 021 4322 444 Fax: 021 4322 433 e-mail: info@crwly.com		Customer Name & Address: 5 LIMEKILLEN DRIVE, DUBLIN 12, D12 AP60 IRISH WATER PIGEON HOUSE ROAD RINGSEND DUBLIN 4	
Date of Collection: 2022-08-20		Waste Collection Permit: WCP-DC-09-1197	
Facility Name & Address:		Local Auth. Area:	
Description of Load:		Waste Cert No:	
Waste Description	EWC Code:	Approx Weight (tonnes):	
Grease Trap Waste (Edible Oil & Fat)	20 01 25		
Septic Tank Sludge	20 03 04		
Street-cleaning residues	20 03 03	500	
Vehicle and Operator:			
Registration: 172D20598		Operator: Janis Melnstrazds	
Work Description: Trap in manhole blocked/line and trap sucked out, and jettied for inspection. Rain water line full of stones jettied as far as main line			
Signature of Customer (Consignor):		Signature of Operator (Carrier):	
Date:		Date: 2022-08-20 11:57:48	
Signature/Stamp of Facility (Consignee):		Date:	



Job ID	Job Name	Job Status	Job Created By
171360	Dynorod Maintenance	Completed	COLM SHEEDY

Company ID	Company	Address
171360	WHITSTON DAVID	5 LIMKILLEN DRIVE , D12 AP60, DUBLIN 12 , Ireland

Contact ID	Contact	Contact Email	Contact Mobile	Contact Phone Number

Project Id	Project Name	Project Owner

Custom Fields	
PO Number	
Invoice Number	
Job Type	JETTING
Job Description	CUSTOMER HAS 2 MAN HOLES ON PROPERTY TO BE CLEANED ONE RUNS TO NEIGHBOURS TO TRAP NEEDS CLEANED AND CCTV PUT AS MUCH NOTES AS WE CAN ON JOB NEED TO SEND ON JOB REPORT €180 INC VAT PER HR ON SITE TIMESHEET
Called in by	DAVID


Job Data	
Asset	
Percentage Received	26
Preferred Start Time	

Custom Fields	
GUTTER CLEAN QUOTE TO BE DONE ON SITE	
Telephone Number	0858391455
E-Mail address	davidwhitston2@hotmail.com
Contact Name	WHITSTON DAVID
Contact Number	
Contact Address	5 LIMEKILLEN DRIVE, DUBLIN 12, D12 AP60
HAS THE CUSTOMER USED DYNO ROD BEFORE	NO
Upload File	
Upload File 2	
Upload File 3	
Upload File 4	
Upload File 5	
Planned Date	10/08/2022
Planned Start Time	17:00
Price	180
Payment Type	
Payment Amount after Discount	180

Job Data	
Preferred End Time	
Assigned To	CILLIAN O SEARCAIGH
Assigned Time	2022-08-10 19:36:00
Assigned At	2022-08-10 16:08:21
Finished At	2022-08-10 21:44:43

Workflow Name	Result	Done At
Call customer	0858391455	2022-08-10 19:07:53
Start Job	Start	2022-08-10 19:07:54
Check In	Completed	2022-08-10 19:07:54
ARE THESE WORKS BEEN DONE FOR ARAMARK		
Risk Assessment	Opened	2022-08-10 19:55:37
Are you wearing full PPE including Gloves, Glasses, Safety Boots and Hi Viz Vest?	Yes	2022-08-10 19:55:43
Are you Wearing Face Mask and overalls or tyvex suit	NO	2022-08-10 19:55:45
Do you have Gate guards or Cones and poles and will use them when opening shores?	Yes	2022-08-10 19:55:46

Workflow Name	Result	Done At
Have you checked your equipment prior to works for defects?	Yes	2022-08-10 19:55:48
Do the works require confined space entry?	No	2022-08-10 19:55:49
DO YOU HAVE LEADER HOSE ON YOUR JETTING HOSE	YES	2022-08-10 19:55:51
ARE THESE WORKS WITHIN THE STANDARD OPERATING PROCEDURE OF TASK	Yes	2022-08-10 19:55:53
IS A SITE SPECIFIC RISK ASSESSMENT REQUIRED FOR THESE WORKS	No	2022-08-10 19:55:55
Get GPS Coordinates	53.3056904 -6.3220123	2022-08-10 19:56:00
Description of Works	JETTING	2022-08-10 19:56:01
Look-see details		
Details		
Sketch		
After Completion		
Tasks completed		
Type of blockage		
What area are you working in?		
TAKE VIDEO OF JOB OR PIPE		
Cause of blockage		

Done At	Result	Workflow Name
		Is drain clear/unblocked
		Record any issues/follow up jobs required
		Confirm all manhole/ shore lids are back down
		Signature
2022-08-10 21:41:56	Opened	Jetting
2022-08-10 20:37:32	Yes	Non-account customer
2022-08-10 20:37:34	Yes	Is the customer onsite?
2022-08-10 20:37:37	Yes	DID YOU CARRY OUT A LOOK SEE
2022-08-10 21:23:16	 (from: mobile) (from: mobile)	TAKE A PICTURE OF LOOK SEE
		TAKE PICTURE OF DEFECT
		Sketch
2022-08-10 21:41:57	Opened	After Completion

Done At	Result	Workflow Name
2022-08-10 21:41:58	2022-08-10 21:41:58	Confirm that customer has signed timesheet
2022-08-10 21:42:01	NA	Record any issues (OFFICE VIEW ONLY)
		TAKE VIDEO OF JOB OR PIPE
2022-08-10 21:42:09	Blocked external drains	Type of blockage
2022-08-10 21:42:13	YES	HAVE YOU CHECKED ALL OF THE GULLIES AROUND THE PROPERTY
2022-08-10 21:42:15	N/A	DID YOU CARRY OUT A PAPER TEST OF THE DRAIN POST UNBLOCK
2022-08-10 21:42:16	2022-08-10 21:42:16	Confirm area has been left clean and tidy
		LOOK SEE SURVEY
		WERE THERE DEFECTS FOUND DURING LOOK SEE
		TAKE IMAGE OF START OF SURVEY
		TAKE IMAGE OF END OF SURVEY
		TAKE IMAGE OF ANY DEFECTS
		LIST AREAS THAT WERE SURVEYED
		WHAT ARE THE DEFECTS
		WHAT IS THE DEPTH OF THE SEWER

Done At	Result	Workflow Name
		WHAT IS THE SURFACE TYPE SURROUNDING AREA OF REPAIRS
		CCTV task
		Non-account customer
		Is the customer on site?
		Have you received drawings for survey?
		Do drains need to be cleaned prior to CCTV?
		Type of survey
		After Completion
		Confirm that customer has signed timesheet
		Can office send report to customer?
		Record any issues
		TAKE VIDEO OF JOB OR PIPE
		Is there an AutoCAD drawing to be updated?
		Was disc left with customer?
		Did you take invert levels?
		Confirm that all manhole/shore lids back down
		Signature
		Tanker Task
		Non-account customer

Done At	Result	Workflow Name
		JETTING OR DE SLUDGING
		ARE THESE WORKS FOR NUI MAYNOOTH
		JET - DE SLUDGE
		Is there payment on site?
		Is the customer on site?
		Have you sucked out a grease trap
		PHOTO PRE SUCK OUT
		PHOTO POST SUCK OUT
		Is the grease trap treated with BIO?
		Are you sucking out a contract grease trap
		WHERE IS WASTE BEEN DISPOSED
		WHAT TYPE OF WASTE
		TYPE OF WASTE
		Grease Trap Waste Weight
		Septic Tank Sludge Weight
		Street-cleaning Residues Weight
		ENTER DUBLIN CITY COUNCIL WASTE CERT NUMBER
		ENTER DATE OF COLLECTION OF WASTE
		ENTER VEHICLE REGISTRATION
		OPERATORS NAME

Done At	Result	Workflow Name
		TAKE PICTURE OF DISPOSAL FACILITY WASTE CERT
		After completion
		Confirm all manhole/ shore lids are back down
		ADD IMAGES FROM POST WORKS LOOK SEE
		TAKE VIDEO OF JOB OR PIPE
		Record any issues
		HOW MANY TONNES HAVE YOU SUCKED OUT
		Dig-up Repair
		Non-account customer
		Is there payment on site?
		Is customer on site?
		Risk Assessment
		DO YOU NEED TO CARRY OUT EXCAVATION WORKS
		Confirm location of underground services been done prior to Excavation
		Confirm that you are wearing full PPE
		Confirm that you have gate guards and will use them when opening shores
		Confirm that you have checked you equipment prior to works for defects
		Have you received a copy of the survey report?

Done At	Result	Workflow Name
		Photo Before
		After completion
		Record any issues
		Are works carried out to the same detail as quotation?
		TAKE VIDEO OF JOB OR PIPE
		Confirm that area has been left clean and tidy
		Confirm all manhole/ shore lids are back down
		Photo on Completion
		PLUMBING WORKS
		WHAT WORKS WERE CARRIED OUT
		ARE FOLLOW UP WORKS REQUIRED
		TAKE PICTURE OF WORKS CARRIED OUT
		HOW MUCH ARE YOU CHARGING FOR PARTS
		CONFINED SPACE ENTRY
		IS IT NECESSARY TO ENTER CONFINED SPACE
		HAVE YOU BEEN BRIEFED ON TASK OF WORKS
		ARE THE PERSON ENTERING TRAINED IN CONFINED SPACE ENTRY

Done At	Result	Workflow Name
		HAVE YOU ASSESSED THE WEATHER CONDITIONS
		ARE THE MATERIALS/EQUIPMENT BEEN USED SUITABLE FOR CONFINED SPACE
		IS THERE A RESCUE PROCEDURE IN PLACE
		HAVE ALL ISOLATION PROCEDURES BEEN IMPLEMENTED
		IS THE REQUIRED PPE AVAILABLE
		IS FIRST AID KIT AVAILABLE
		IS ESCAPE APPARATUS AVAILABLE
		IS GAS MONITOR WITHIN CALIBRATION DATE
		ALL CONTRABAND COLLECTED AND STORED SAFELY
		HAS ALL EQUIPMENT BEEN USED DURING ENTRY BEEN TAGGED, TESTED AND INSPECTED PRIOR TO USE
		HAVE YOU ESTABLISHED COMMUNICATION PROCEDURES WITH ALL INVOLVED IN ENTRY AND TOP MAN
		OXYGEN LEVEL
		HYDROGEN SULPHIDE LEVEL
		EXPLOSIVES/METHANE LEVEL
		CO LEVEL
		BA GAUGE READING


Done At	Result	Workflow Name
		SIGNATURE OF TOP MAN
		CONFIRM ALL WORKS COMPLETED
		CONFIRM ALL INVOLVE IN ENTRY ARE SAFE AND OUT OF CONFINED SPACE
		RECORD ANY ISSUES
		CONFIRM ALL MANHOLE LIDS HAVE BEEN PUT BACK DOWN
		SIGNATURE ON COMPLETION OF WORKS
		BIO
		Confirm that you have reported to site contact on arrival
		Is the dosing pump working?
		Take picture of grease trap
		After completion
		TAKE VIDEO OF JOB OR PIPE
		HAVE YOU CHECKED THE SETTINGS ON THE PUMP TO MAKE SURE THEY ARE CORRECT
		WAS THERE BIO LEFT IN THE DRUM WHEN YOU ARRIVED ON SITE
		Record any issues
		Confirm that the area is left clean and tidy
		Confirm all manhole/ shore lids are back down

Done At	Result	Workflow Name
		Name of contact on site who you showed the folder updated to
		Signature
		MAKE A QUOTE
		TAKE VIDEO OF JOB OR PIPE
		Lead Sheet
		Works required
		Length of sewer to be repaired
		Depth of Sewer
		Surface type
		Are these works sold or unsold?
		Sketch
		Take photo
		Additional comments
		E Mail Address
		Mark this job incomplete
		Job incomplete
		Confirm that you are restarting this job
2022-08-10 21:42:19	Opened	Payment Details
2022-08-10 21:42:23	171360	Enter Invoice Number

Workflow Name	Result	Done At
Enter Timesheet Number		
Enter Timesheet hours	1	2022-08-10 21:42:26
Enter Timesheet Amount		
Enter Invoice Amount	Opened	2022-08-10 21:42:27
Enter Total job amount	180	2022-08-10 21:42:32
What is the method of payment	CREDIT CARD	2022-08-10 21:42:34
is the customer paying by Bank Transfer	NO	2022-08-10 21:42:35
Is customer paying by credit card?	Yes	2022-08-10 21:42:44
Send Pay2Sender Link	Status: QUEUED	2022-08-10 21:43:01
P2S_First_name	WHITSTON DAVID	2022-08-10 21:42:56
P2S_Last_name		
P2S_Mobile_number	0858391455	2022-08-10 21:42:56
P2S_Email_address	davidwhitston2@hotmail.com	2022-08-10 21:42:56

Done At	Result	Workflow Name
2022-08-10 21:42:56	{ "sms": true, "email": true }	P2S_Notification
2022-08-10 21:42:56	180	P2S_Total
2022-08-15 16:34:58	PAID	P2S_Status
2022-08-10 21:42:57	a3de34ad-6550-44fd-a71a-84ee550b4008	P2S_ID
2022-08-10 21:43:05	No	Credit Card has been put through on site
2022-08-10 21:43:09	No	Was payment collected on site?
2022-08-10 21:43:13	No	ARE THERE FOLLOW UP WORKS REQUIRED ON THIS JOB
2022-08-10 21:43:15	No	WAS THERE A NEAR MISS OR ACCIDENT ON THIS JOB THAT NEEDS TO BE REPORTED
2022-08-10 21:44:30	Both lines blocked with stone and holding water. Customer needed stones removed so a survey could be carried out. Foul line cleared as far as mains. Storm line appears either damaged or to fall into a chamber with a smaller size line continuing from the chamber.	BRIEF REPORT ON WORKS CARRIED OUT AND ISSUES FOUND (CUSTOMER VIEW)
2022-08-10 21:44:32	No	HAVE YOU ENTERED THE CUSTOMERS HOME

Job Status	Updated By	Updated On	Status Message As Text
Completed	CILLIAN O SEARCAIGH	2022-08-10 21:44:44	<p>Date Time: 2022-08-10 21:44:44</p> <p>By: CILLIAN O SEARCAIGH</p> <p>Type: Job Complete</p> <p>Message: Job 171360 has been set to completed By CILLIAN O SEARCAIGH on 2022-08-10 21:44:44</p>

Workflow Name	Result	Done At
Is a Cash Invoice Job or Timesheet Job?	Cash Invoice	2022-08-10 21:44:33
GET CUSTOMER E MAIL	davidwhitston2@hotmail.com	2022-08-10 21:44:37
Engineer sign-off	 (from: mobile)	2022-08-10 21:44:42
Complete job	Complete	2022-08-10 21:44:43
Distance	< 100m	2022-08-10 21:44:43
Check Out	Complete	2022-08-10 21:44:43
Created From Web Module	2022-08-10 16:18:03 - email set: davidwhitston2@hotmail.com	2022-08-10 15:18:03

Job Status	Updated By	Updated On	Status Message As Text
In Progress	CILLIAN O SEARCAIGH	2022-08-10 19:07:55	Date Time: 2022-08-10 19:07:55 By: CILLIAN O SEARCAIGH Type: Job InProgress Message: Job 171360 has been set to inprogress By CILLIAN O SEARCAIGH on 2022-08-10 19:07:55
Accepted	CILLIAN O SEARCAIGH	2022-08-10 19:07:52	Date Time: 2022-08-10 19:07:52 By: CILLIAN O SEARCAIGH Type: Job Accept Message: Job 171360 has been accepted By CILLIAN O SEARCAIGH on 2022-08-10 19:07:52 to CILLIAN O SEARCAIGH
Assigned	COLM SHEEDY	2022-08-10 16:08:21	Date Time: 2022-08-10 16:08:21 By: COLM SHEEDY Type: Job Assign Message: Job 171360 has been assigned By COLM SHEEDY on 2022-08-10 16:08:21 to CILLIAN O SEARCAIGH
Unassigned	COLM SHEEDY	2022-08-10 15:18:03	Date Time: 2022-08-10 15:18:03 By: COLM SHEEDY Type: Job Unassign Message: Job 171360 has been set to unassigned By COLM SHEEDY on 2022-08-10 15:18:03

Sketch

Signature

TAKE A PICTURE OF LOOK SEE