

Peter Brennan
Hayfield House
Knocklyon Road
Templeogue
Dublin
D16 DX62

7th September 2022



Planning Department
SDCC
County Hall
Town Centre
Tallaght
Dublin 24.

Re: Condition Compliance, application reg. ref. SD22B/0043

Dear Sir/Madam,

Please find enclosed two CCTV inspection reports, which were carried out by Greenday Environmental, to ascertain the existing and proposed surface water drainage layouts up to and including the point of connection to the public surface water sewer including the location of all AJ's, manholes, pipe size, material type and direction of flow, and the associated drawings, as specified in Condition No. 3. Of planning application, register reference SD22B/0043. Greenday encountered a blockage when carrying out the initial inspection, so it was necessary to engage Dyno-Rod to clean the drains of the debris build-up to facilitate the completion of the CCTV inspection, please also find the report from Dyno-Rod enclosed.

Yours Sincerely,



Peter Brennan

(Agent)