



NTS



Existing Sign Post - Unused



Existing Sign Post Unused - approx 2.5m-3m



**LEGEND**  
Street furniture & Services

Over Head Wires (LIAS) - Pylon ESB	Bus Stop	Bench Seat	Phone Box
Flowerbed	Barrel	Bus Stop	Duct
Pipe	Beacon	Barrel	Base Cover
Man	Beacon	Barrel	Base Cover
Barrier	Coastline Cover	Waste Bin	Waste Bin
Pump	Bore Hole	Hydrant	Hydrant
Trail Pit	Electricity Pole	Hydrant	Hydrant
Bus/Tram Shelter	Telegraph pole	Hydrant	Hydrant
Postbox	OCS Pole	Hydrant	Hydrant
Valve - General	OCTV Camera Pole	Hydrant	Hydrant
Water Valve	Lamp Post	Hydrant	Hydrant
Gas Valve	Four Masts	Hydrant	Hydrant
Sluice Valve	Surface Water MH	Hydrant	Hydrant
Air Valve	Manholes	Hydrant	Hydrant
Stop Cock	Air Conditioning Vents	Hydrant	Hydrant
C/P Post	Services Inspection Cover	Hydrant	Hydrant
Marker Post	Traffic Inspection Cover	Hydrant	Hydrant
Traffic Light	Cable TV Inspection Cover	Hydrant	Hydrant
Painting Meter	EBM Inspection Cover	Hydrant	Hydrant
Plane Aerial Mark	W/L Inspection Cover	Hydrant	Hydrant
Smart Card Validator	Binom Inspection Cover	Hydrant	Hydrant
Unknown Valve	Holding Eye	Hydrant	Hydrant

**Natural Features**

Surface Change	Water Level	Fair Way
Land Drain	Crown Level	Green
Bottom of Slope	Invert level	Tree Box
Top of Slope	Bed Level	Other
Ditch	Spotheight	Survey Station
Water Edge / Lake / Flood	Spotheight	Photo point
Hedge / Trees Drip Line / Vegetation	Spotheight	Photo point
Tree Centaurus	Spotheight	Photo point

**Built Features**


Building	Fence	Floor Level
Edge of Road	Gate	Apex Height
Kerb Bottom	Road Centreline	Eaves Height
Leat Top	Top of Wall	Parapet Height
Bridge Abutment	Roading	Start Direction
Bridge Deck	Property Line	Stop Level
Bridge Parapet	Road Scar	Concrete Pad
Building Facade	Top of Fence	Track
Footpath / Platform Train & Tram	Wall / Retaining Wall	
Damp Proof Course / Verge	Railway / Train Rail / Gating / Ramp	
Bridge Pier / Wall & Gate Pile / LIAS Trackbed	Building Canopy / Roof / Overhang	
Cycleway / Private Landing Area		

**Murphy Surveys Ltd. Disclaimer**

The user or recipient of this survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed will be labelled as "UTS".

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or damages suffered by the Client.

The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified scale or accuracy.



Map Sheet Layout:

Surveyed by: HM	Date: 24.06.2020	Drawn: Main Head
Drawn by: CSE	Date: 16.03.2022	Grid System: Irish National Grid
Checked by: PK	Date: 16.03.2022	Irish National Grid: [ ]

No	Date	Description
0	06.2020	First Drawing
1	16.03.2022	Details added, Elevations added
2	11.11.2022	Signpost Furniture Update
3	29.11.2022	Tolerances & Layout Update



**Kildare Cork Dublin Belfast Glasgow Manchester London**

**Head Office**  
Global House  
Kilcullen Business Campus  
Kilcullen Co. Kildare

Phone: (+353) 045 484040  
Fax: (+353) 045 484004  
Email: info@murphysurveys.ie

Client:	BOC Gases Ireland
Project:	BOC Gases Ireland at Unit 10 JFK Drive
Date:	16.03.2022
Scale:	1:50@A1
Description:	Existing Elevations
Drawing Number:	MGS39042_EL_Rev3.6

Copyright 2022 MURPHY GEOSPATIAL LTD