## **Water Services Planning Report**

Register Refere Development:	Demolition of e house and outbe storey mixed us practice, consis staff areas as w two floors at gr apartment with balcony area at spaces and secu- all on site; Bacl	existing two storey described buildings; Construct noted building with, a reting of 5 consultation lell as a rehab gym around and first floor lown door access and the second floor level.	new purpose built three new physiotherapy in rooms, office space, and studio area, all over evels; One bedroom il dedicated private el; 5 car parking arking for 6 bicycles ont facade of the	
Location:	Saint Claires V X0N1	Saint Claires Villa, Lucan Road, Lucan, Co. Dublin, K78 X0N1		
Report Date :	03 <sup>rd</sup> March 202	3		
Surface Water	r Report:	No Obje	ction Subject To:	
Flood Risk			No Objection	
_	per shall ensure that there is ge for the proposed develop		of the foul and surface	
• All works fo	or this development shall co onal Code of Practice for D	omply with the requi	rements of the Greater	
Water Report:			Refer to IW	
Foul Drainage Report:			Refer to IW	
Signed:	Brian Harkin SEE	Date:		
Endorsed:	Juliene Helbert SE	Date:		